

Cleveland, Ohio

Corporate Headquarters
3650 E. 93rd St.
Cleveland, OH 44105
(216) 271-2300
800-BUY-N-USA

Baltimore, MD.

8600 Larkin Rd.
Savage, MD 20763
(410) 792-0995
DC (301) 470-3133
800-274-2465

Buffalo, New York

1975 Werhle Ave., 130
Williamsville, NY 14221
(716) 565-1066
800-274-9465

Cinn/Dayton, Ohio

400 Industry Drive
Carlisle, Ohio 45005
(937) 743-9704
800-274-1465

Columbus, Ohio

6999 Huntley Rd. #101-I
Worthington, OH 43229
(614) 888-8083
888-465-1274

Detroit, Michigan

11898 Belden Ct
Livonia, MI 48150
(734) 458-2011
800-289-3465

Indianapolis, IN

1422 Sadlier Circle W Dr.
Indianapolis, IN 46239
(317) 352-8781
800-274-3465

Independence, OH

5405 Valley Belt, Ste G&H
Independence, OH 44131
(216) 640-2800
800-332-4657

Newark, New Jersey

625 Montrose Ave.
S. Plainfield, NJ 07080
(908) 822-9600
800-274-8465

Pittsburgh, PA

1000 California Ave.
Pittsburgh, PA 15212
(412) 231-2273
800-274-4465

Richmond, Virginia

5616 Eastport Blvd.
Richmond, VA 23231
(804) 236-4632
800-465-4274

Sacramento, CA

3106 Orange Grove Ave.
North Highlands, CA
95660
(916) 971-0800

Milwaukee, WI

4010 W. Douglas Ave.
Milwaukee, WI 53209
(414) 461-4999
877-461-4999



SUPER FADE RESIST

SUPER FADE RESIST inks are made with special pigments to provide maximum lightfastness for use on bumper stickers, etc. They are designed to print on synthetic (plastic) papers, such as Kimdura, Tyvek, and other non-porous printing substrates that require specially formulated inks. Printing with Super Fade Resist Inks also requires cautious handling procedures in order to achieve the desired results.

SUPER FADE RESIST INKS

- are 100% non-volatile
- have excellent press stability and transfer qualities
- dry to a super hard finish with exceptional scuff resistance
- will not swell nor distort solvent sensitive stocks
- are press ready - additives are rarely necessary (Do NOT use tack reducers that contain solvent)
- have a tack of 19 @ 1200 rpm

PRINTING TECHNIQUES & HANDLING PROCEDURES

ALWAYS PRE-TEST ON ACTUAL SUBSTRATE

- Use a minimum amount of ink & fountain solution. A 0.4 mil thickness of ink on the form roller is recommended; and use just enough fountain solution to keep the print clean
- Do NOT use any fountain solutions that contain glycerine or citric acid.
- Always use aluminum or metal plates.
- Keep the pH as high as possible - 4.5 to 5.5 is usually satisfactory
- A 25 to 35 micron size anti-set-off spray should be used at the press delivery.
- Lifts should be kept as small as possible in order to facilitate drying and help prevent offsetting.
- The addition of Grafo Drier Extra, 761X1016, may be helpful as an aid to drying.
- Super Fade Resist Inks skin very quickly and should NOT be left on the press for more than two hours without running.
- Note: Due to the nature of the type of pigments used in this series, colors may not match desired color exactly in shade and strength.

Due to variations in stocks and other variables inherent in the printing process, which are beyond the control of the ink maker, we cannot assume any responsibility for the final outcome of the printed job.

PLEASE CALL OUR TOLL FREE NUMBER FOR MORE INFORMATION

1-800-BUY-N-USA (1-800-289-6872)

2/2005